

SMOKE TESTING REPORT



Submitted to:
Green Charter
Township

July 2019
839870



TABLE OF CONTENTS

Executive Summary	1
Introduction	2
Project Background	2
Terminology.....	2
Objectives	2
Testing Methodology.....	3
Results & Recommendations	4

List of Attachments for Smoke Testing Report

- Attachment A: Smoke Testing Maps
- Attachment B: Observation Photo Log

EXECUTIVE SUMMARY

Green Charter Township retained Fleis & VandenBrink (F&V) to smoke test its wastewater collection system as part of an effort to locate sources of inflow and infiltration (I&I). I&I sources allow stormwater to enter the sanitary sewer system during rainfall events, which cause an increase in flow through the system. Green Charter Township pays the City of Big Rapids to treat their wastewater, and it has noticed a recent increase in metered flows through the Green Charter Township lift station. Because the City of Big Rapids charges the township based on metered flows, the increase in flow has caused an increase in treatment cost to the township. Smoke testing was selected as a method to locate sources of I&I in the sanitary sewer system. The results of the testing are summarized below.

Study Details

This report presents the results of the smoke testing that was completed on June 4 and June 5, 2019. Smoke testing is a relatively fast, economical, and effective method of locating potential sources of inflow and infiltration (I&I) into the sanitary sewer collection system. A map of the area tested, and the locations of smoke observations, can be found in Appendix A.

Conclusions

Fifteen instances of smoke exiting the wastewater collection system at inappropriate locations were found during smoke testing. The list below identifies each of these locations, the priority in fixing them and the recommended remediation action.

Connected Storm Drains (High Priority)

- 20868 Emerald Lane Driveway storm drain connected to sanitary sewer

Leaking Manhole Structures (Medium Priority)

- Township Sanitary Sewer Manhole #26
- Holland Drive Manhole #7 in the Country Manor Estates
- Holland Drive Manhole #6 in the Country Manor Estates
- Holland Drive Manhole #5 in the Country Manor Estates
- Holland Drive Manhole #4 in the Country Manor Estates
- Holland Drive Manhole #2 in the Country Manor Estates
- South Haven Drive Manhole #9 in the Country Manor Estates

Open Sanitary Cleanout- Property owner to install new cleanout cap (Low Priority):

- Cabin #1 Northland Drive
- Cabin #2 Northland Drive
- Broken Clean Out #3 of the Country Manor Estates
- Broken Clean Out on lot 225 of the Country Manor Estates
- Buried Clean Out at the River's Edge Condominium Development Entrance (in rock landscaping)
- Northeast corner of northeast building of Old Carter's Lumber

Miscellaneous (Medium Priority):

- Undeveloped lot 259/260 of the Country Manor Estates leaking lateral connection

INTRODUCTION

PROJECT BACKGROUND

In an effort to understand why Green Charter Township is experiencing elevated flow rates in its sanitary sewer system, the Township partnered with F&V. To determine if inflow and infiltration were responsible for the recent increase in flow, the Township and F&V conducted sanitary sewer smoke testing in June of 2019 in an effort to locate sources of I&I.

TERMINOLOGY

Infiltration and Inflow (I&I) is a broad term that is often defined differently by different people and organizations. For the purposes of this report, the below list of types of I&I with their accompanying definitions is used.

- **Groundwater Infiltration** – groundwater entering the sanitary sewer through structural defects (e.g. cracks or separated joints) on a constant basis, regardless of precipitation or surface water elevations.
- **Inflow** – surface runoff from precipitation entering the sanitary sewer through direct connections (e.g. storm sewer connections, roof drains, open sewer cleanouts). It is characterized by a flow spike immediately following precipitation, especially intense periods of precipitation.
- **Storm-Induced I&I** – an increase in sewer flow starting 1-2 days after a precipitation event and lasting 1-2 days. Sources of storm-induced tend to be temporary storages of precipitation, such as the soil (e.g. elevated groundwater levels) or basements.
- **River-Induced I&I** – elevated flows in response to elevated Muskegon River water surface levels. During the study, periods of elevated river stage lasted 4-7 days. This form of I&I can be attributed to a number of causes, the major ones being, in order of likelihood:
 - Elevated groundwater levels causing increased infiltration through structural defects.
 - Exfiltration from storm sewers or overland drains travelling through the ground and infiltrating the sanitary sewers.
 - Direct connections between storm sewers or overland drains and the sanitary sewers.
 - Surface flooding entering manholes not adequately watertight.

Due to the nature of smoke testing, it has a tendency to identify inflow sources, but usually does not identify any of the other sources of I&I listed above. For instance, smoke testing is more likely to identify a catch basin connected to the sanitary sewer or a broken sewer lateral clean-out cap than structural defects in the buried piping system.

OBJECTIVES

The objective of this study was to determine as many I&I sources as can be found by smoke testing as well as to present the findings in a manner in which each inflow point can be tracked for future confirmation of correction. The report also categorizes each inflow point into its relative priority based on the estimated volume of clean water inflow that might occur at that point. For instance, a catch basin connected to the sanitary sewer system will have a higher priority because it will discharge significantly more clean water into the sanitary sewer system than a broken cap on a sanitary lateral clean-out will.

TESTING METHODOLOGY

Smoke Testing involves blowing a non-toxic synthetic smoke like gas into the sanitary sewer system at strategically located manholes and recording observations of where the smoke emerges from the sewer system at inappropriate locations such as catch basins, uncapped sewer lateral clean-outs, roof drains, etc. Smoke from these inappropriate locations indicates potential pathways of I&I entering the sanitary sewer system.

Prior to testing, affected businesses and homeowners were notified by the Township and Fleis & VandenBrink employees via printed notices on doors. The local police and fire department were informed of the testing, prior to testing, in the event that the artificial smoke might be interpreted as real smoke and reported to the authorities.

A portable blower specifically designed and built for use in smoke testing was utilized for the work. The smoke fluid used for the testing produces artificial smoke when pumped from a container onto the heating element of the blower manifold. The artificial smoke generated is white in color and leaves no residue. The smoke is non-toxic, non-explosive, and dissipates quickly once the blower is deactivated.

To perform the testing, the blower was positioned on a sanitary manhole and a visual inspection was conducted of the surrounding area as smoke was continuously introduced into the system. The effective area of coverage for each manhole set-up was defined by the observation of the smoke exiting home roof vents, sanitary manhole covers, and suspect locations of the sanitary sewer system noted in the field as potential sources of I&I.

Blower setup locations were selected to provide overlap within the coverage areas in order to facilitate testing of the entire target area of the sanitary sewer collection system without gap. The operation of the collection system was not interrupted, nor was it necessary to plug the sewer pipes.

RESULTS & RECOMMENDATIONS

A total of 15 instances were noted where smoke exited the sanitary sewer system at an inappropriate location. Each of these instances were logged with a sketch of the area along with a written description of what was visually observed. Additionally, many instances were documented with pictures identifying the location where smoke was observed. The field logs and pictures are attached to this report in Attachment A.

Each instance where smoke was observed has been categorized into one of three categories based on how much clean water inflow it is felt likely to occur at that location. The priority classifications are identified by a visual inspection and are intended to help the City economically and efficiently prioritize correcting the problems. The three categories are:


- *Low Priority* – Small chance for inflow to occur due to natural runoff and infiltration of the area around the specified object.
- *Medium Priority* – Good chance for inflow to occur due to natural runoff and infiltration of the area around the specified object.
- *High Priority* – High chance for inflow to occur due to natural runoff and infiltration of the area around the specified object.

Recommended actions accompany each location where smoke was observed. Many of the locations are outside of the right-of-way and therefore privately owned by the property owner. The Township is not responsible for either making repairs or the associated cost for problems found on private property as ownership and maintenance responsibilities of the sewer system end at the right-of-way. However, the Township can enforce its sewer use ordinance and its rules and regulations of the sewer system. Therefore, it is recommended that the Township notify each of the private property owners in writing of the I&I issues discovered and require that repairs be made by the property owner within a timely manner.

The table below identifies each of the instances where smoke exited the sanitary sewer system at an inappropriate location and identifies the priority and recommended action.

Table 1: Smoke Testing Observations				
Event	Location	Observation	Priority	Remedy Recommendation
1	Sanitary Manhole #26	Leaking around Base	Medium	Rehab Manhole
2	Cabin #1 Northland Drive	Open Cleanout	Low	Install Cap
3	Cabin #2 Northland Drive	Open Cleanout	Low	Install Cap
4	20868 Emerald Lane	Storm Drain Connected to Sanitary Sewer	High	Disconnect Drain from Sanitary Sewer
5	Lot #225 of Country Manor Estates	Open Cleanout	Low	Install Cap
6	Manhole #6 on Holland Drive	Leaking around Base	Medium	Rehab Manhole
7	Manhole #7 on Holland Drive	Leaking around Base	Medium	Rehab Manhole
8	Manhole #9 on South Haven Drive	Leaking around Base	Medium	Rehab Manhole
9	Lot #3 of the Country Manor Estates	Broken Cleanout	Low	Replace Cleanout
10	Manhole #5 of the Country Manor Estates	Leaking around Base	Medium	Rehab Manhole
11	Manhole #4 of the Country Manor Estates	Leaking around Base	Medium	Rehab Manhole
12	Lateral Connection (Lots 259/260)	Leak	Low	Plug Lateral Connection until Lot is Developed
13	Manhole #2 of the Country Manor Estates	Leaking around Base	Medium	Rehab Manhole
14	River's Edge Condominium Entrance	Buried Open/Broken Cleanout	Low	Replace Cleanout
15	Northeast Corner of Northeast Building of Old Carter's Lumber	Open Cleanout (Missing Cap)	Low	Install Cap

ATTACHMENT A
SMOKE TESTING MAP




- Smoke Testing Result/Event #
- Approximate Sanitary Main Location

Approximate Leak Locations

Green Charter Township, Michigan

DRAWN BY	DATE
SWL	6/26/2019
PROJECT NO.	SCALE
839870	1:5,400
FILE LOCATION M:\Proj\839870-441000\839870 Green Charter Twp - Smoke Test 2019\CAD\GIS\GIS data\839870_Approximate Leak Locations.pdf	
SOURCES Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community	



ATTACHMENT B
OBSERVATION PHOTO LOG



Event #1: Leaking Base on Sanitary Manhole 26 at the Corner of Dean's View and Forest Trail



Event #2: Open Cleanout at Northland Drive Cabin #1



Event #3: Open Cleanout at Northland Drive Cabin #2



Event #4: Storm Drain in Driveway connected to Sanitary Sewer at 20868 Emerald Lane



Event #5: Broken Cleanout on Lot #225 of the Country Manor Estates



Event #6: Leaking Base on Manhole #6 on Holland Drive of the Country Manor Estates



Event #7: Leaking Base on Manhole #7 on Holland Drive of the Country Manor Estates



Event #8: Leaking Base on Manhole #9 South Haven Drive of the Country Manor Estates



Event #9: Broken Clean Out #3 of Country Manor Estates



Event #10: Leaking Base on Manhole #5 on Holland Drive of the Country Manor Estates



Event #11: Leaking Base on Manhole #4 on Holland Drive of the Country Manor Estates



Event #12: Leaking Lateral Connection for Undeveloped Lot 259/260 of the Country Manor Estates



Event #13: Leaking Base on Manhole #2 on Holland Drive of the Country Manor Estates



Event #14: Buried Clean Out at the River's Edge Comdominium Development Entrance



Event #15: Clean Out with no cap at the Northeast Corner of the Northeast Building of Old Carter's Lumber